



SAS Superstructure

Location: 04-SF-80-13.2 / 13.9

Client Name: CalTrans

Run date 22-Nov-14

Time 10:28 AM

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 293 Const Calendar Day: 310 Date: 10-Apr-2013 Wednesday

Inspector Name: Wolcott, Brian Title:

Inspection Type: Intermittent

Shift Hours: 07:00 am 03:30 pm Break: Over Time:

Federal ID:

Location:

Reviewer: Schram, Darryl Approved Date: Status: Submit

04-0120F4
04-SF-80-13.2/13.9
Self-Anchored
Suspension Bridge

Weather

Temperature 7 AM 50 - 60 12 PM 60 - 70 4PM 50 - 60

Precipitation Condition

Working Day If no, explain:

Diary:

Dispute

General Comments

I attended the District SWPPP inspection at 1:30pm. The last Post storm inspection was on 4/4/13. In the inspection, I was asked to monitor the demo of the most westerly truss span/tower A-B southside for quantity assessment of debris. It shall be determined if this monitoring is necessary. New SWPPP items are the following: Various paint spills were observed adjacent to paint drums that are being stored on westbound deck, construction and lunch waste was observed at various locations on the westbound deck, a sticky substance was observed on the ground adjacent to a conex box at the eastern end of the eastbound deck.

