

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
 690 Walnut Ave. St. 150  
 Vallejo, CA 94592-1133  
 (707) 649-5453  
 (707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.12**DAILY PROJECT JOURNAL****Prime Contractor:** American Bridge/Fluor Enterprises, a JV**Report No:** DPJ-000686**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Dated:** 13-Feb-2008**Location:** Changxing Island, Shanghai, PRC**Submittals(New / Total):****CWR's:** /**HSR's:** /**NCR's:** /

Item	Title	Detail
1	Other important observations	<p>At 1300 I went on a Shop Floor Walkthrough and observed the following:</p> <p>77m Mockup: I observed ZPMC welders welding the corner plate connection between plates B and C.</p> <p>89m Mockup: Work continues on welding the corner joints of the mockup. Interior connections A to C and C to D are completely welded.</p> <p>114m Mockup: Both the upper and lower sections have been machined. Control points A and E are aligned but the resulting skins are not aligned by as much as 10mm on skin B.</p>

**Inspected By:** Ishibashi, Josh

Quality Assurance Inspector

**Reviewed By:** Wahbeh, Mazen

QA Reviewer