

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.15**SOURCE INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-000036**Date Inspected:** 11-Apr-2007**Project Name:** SAS Superstructure**OSM Arrival Time:** 800**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**Quality Control Contact:** Lu Jian Hua**Quality Control Present:** Yes No**Material transfer:** Yes No N/A**Sampled Items:** Yes No N/A**Stock Transfer:** Yes No N/A**OK to Cut:** Yes No N/A**Rebar Test Witness:** Yes No N/A**Delayed/Cancelled:** Yes No N/A**Other:** N/A**Bridge No:** 34-0006**Component:** N/A**Bid Item:** 52**Lot No:** N/A**Summary of Items Observed:**

The Caltrans Quality Assurance (QA) Inspector, Alfredo Acuna was present at Zhenhua Port Machinery Company (ZPMC) on Changxing Island, Shanghai, China to observe quality control functions related to the qualification testing for the San Francisco Oakland Bay Bridge (SFOBB) Self-Anchored Suspension Span (SAS).

ZPMC QA Inspector, Lu Jian Hua relayed to the QA inspector that ZPMC would be performing welder and welding operator qualification side bend testing on Saturday 4-14-07 and welder and welding operator qualification tests on Sunday 4-15-07. Mr. Lu relayed to the QA inspectors that no welding would be performed on this date as well.

Summary of Conversations:

As noted above.

Note: See Task Leader journal for additional information this week.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By: Acuna, Alfredo

Quality Assurance Inspector

Reviewed By: McClary, David

QA Reviewer