

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.15**SOURCE INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-000345**Date Inspected:** 31-Dec-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**Quality Control Contact:** Jeff Evans**Quality Control Present:** Yes No**Material transfer:** Yes No N/A**Sampled Items:** Yes No N/A**Stock Transfer:** Yes No N/A**OK to Cut:** Yes No N/A**Rebar Test Witness:** Yes No N/A**Delayed/Cancelled:** Yes No N/A**Other:****Bridge No:** 34-0006**Component:** plate check samples**Bid Item:****Lot No:** B222-001-08 thru B222-009-08**Summary of Items Observed:**

Plate Yard

This QA Inspector selected 460mm x 355mm plate check samples and assigned a QA Lot number to the following material:

Lot number B222-001-08, 50mm A709SL-Gr485 plate, Heat number: 7206432N

Lot number B222-002-08, 18mm A709M-345F2-X plate, Heat number: 7301544NO

Lot number B222-003-08, 20mm A709M-345F2-X plate, Heat number: 07301432NO

Lot number B222-004-08, 12mm A709M-345F2-X plate, Heat number: 07304769NO

Lot number B222-005-08, 50mm A709SL-Gr345 plate, Heat number: 7301297N

Lot number B222-006-08, 16mm A709 M -345F2-X plate, Heat number: 07303928NO

Lot number B222-007-08, 16mm A709SL-345F2-X plate, Heat number: 07303574NO

Lot number B222-008-08, 32mm A709SL-Gr485 plate, Heat number: 7203804N

Lot number B222-009-08, 50mm A709SL-Gr485-X plate, Heat number: 720399

Samples were marked with Lot number, date and direction of rolling and will be shipped to an Independent Testing lab.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

SOURCE INSPECTION REPORT

(Continued Page 2 of 2)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372 , who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
