

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-007519**Date Inspected:** 18-May-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen Xing Xin**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** TOWER COMPONENTS**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Gady Rao, was present during the times noted above for observations relative to the work being performed.

Magnetic Particle Testing:

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member(s) & the weld designations reviewed are as follows:

Bay 10

Inspection part	Section	Inspection Area.
WD1-A467-38M-3	STRUT PLATE	Bay-10
WD1-A467-47.6M-3	STRUT PLATE	Bay-10
WD1-A467-23M-4	STRUT PLATE	Bay-10
ED1-A27A/E-3 to 20,76 to 93	SHEAR PLATE	Bay-10

Bay 10

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SAW

SAW welding of weld joint NSD1-FCSA4-1A/C-50B located on PCMK Skin-C; Lift-4; North Tower. Welder is identified as 040252. ZPMC QC is identified as Maa Yun. The welding variables recorded by QC appeared to comply with the B-T-2221-B-U3C-S-2.

FCAW

FCAW welding of weld joint # NSD1-FDSA3-1B/C-26, 27, 36, and 37 located on North Tower, Lift-3, and Skin-D. Welders are identified as 069075 / 068501/067275/066914. ZPMC QC is identified as Zhong An. The welding variables recorded by QC appeared to comply with the WPS-B-T-2332-TC-P5-F.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045., who represents the Office of Structural Materials for your project.

Inspected By:	Rao,Gady	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
