

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-009471**Date Inspected:** 07-Oct-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Xu Xian Ping**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG & TOWER Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Sandeep Kumar was present during the times noted above for observations relative to the work being performed.

**BAY 2**

This QA Inspector observed the following work in progress:

FCAW process welding of weld joint # 045 located on Floor Beam FB3052 – 001. Welder is identified as 045276.

ZPMC QC is identified as Yang Qing Feng. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2232 – Tc – U4b – F.

FCAW process welding of weld joint # 015 located on Floor Beam FB3041 – 001. Welder is identified as 045203.

ZPMC QC is identified as Yang Qing Feng. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2132 – 3.

FCAW process welding of weld joint # 005 located on Floor Beam FB3052 – 001. Welder is identified as 062438.

ZPMC QC is identified as Yang Qing Feng. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2133.

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

---

BAY 5

## Magnetic Particle Testing

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member is identified as OBG Component. The weld designations reviewed are as follows:

1. BK001 – 025 – 048; 049

This QA Inspector observed the following work in progress:

FCAW process welding of weld joint # 010 located on Traveler Rail 11TR2 – 012. Welder is identified as 068858.

ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2232 – Tc – U5 – F.

SAW process welding of weld joint # 003 located on Cross Beam CB202C – 016. Welder is identified as 215248.

ZPMC QC is identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2221 – B – L2c – S – 2.

FCAW process welding of weld joint # 006 located on Traveler Rail 11TR2 – 013. Welder is identified as 068858.

ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2232 – Tc – U5 – F.

BAY 6

Tower

This QA Inspector observed the following work in progress:

SMAW process welding of weld joint #10A located on Tower Strut WD1 – A305 – 53M – 1. Welder is identified as 067707. ZPMC QC is identified as Zhao Chen Sun. The welding variables recorded by QC appeared to comply with the WPS – 485 – SMAW – 2G (2F) – FCM – Repair – 1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

## Summary of Conversations:

No Relevant Conversations.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang - 15000422372, who represents the Office of Structural Materials for

---

---

# WELDING INSPECTION REPORT

*( Continued Page 3 of 3 )*

---

---

your project.

---

**Inspected By:** Kumar,Sandeep

Quality Assurance Inspector

---

**Reviewed By:** Hall,Steven

QA Reviewer