

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-012138**Date Inspected:** 14-Feb-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	NA	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	OBG and Tower	

Summary of Items Observed:

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Mr. Paul Dawson, arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China, for the purpose of monitoring welding and fabrication of the San Francisco / Oakland Bay Bridge (SFOBB) components. This QA Inspector observed the following:

OBG Bays 1 through 9

This QA Inspector observed no ZPMC personnel were working on Caltrans OBG segments or tower assemblies in OBG Bays 1 through 9.

OBG Bays 13 and 14

This QA Inspector observed no ZPMC personnel were working on Caltrans OBG segments or tower assemblies in OBG Bays 13 or 14 and the majority of the overhead lights were turned off.

Tower Bays 10 and 11

This QA Inspector observed no ZPMC personnel were working on Caltrans tower components in Bays 10 or 11. See the photograph, below, for additional information.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Heavy Dock Tower

This QA Inspector observed no ZPMC personnel were working on Caltrans tower assemblies at the heavy dock.

OBG Trial Assembly

This QA Inspector observed no ZPMC personnel were working on Caltrans OBG segments in or around the OBG trial assembly area.

Many of the ZPMC workers are not at work due to the Chinese New Year holiday.



Summary of Conversations:

See Above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang phone: 150-0042-2372 , who represents the Office of Structural Materials for your project.

Inspected By:	Dawson,Paul	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
