

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014529**Date Inspected:** 04-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	OBG	

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

TRIAL ASSEMBLY YARD

ULTRASONIC INSPECTION

OBG SEGMENT 8BW-8AW

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the side panel splice weld between OBG segment 8AW and 8BW (Counter weight side). The weld designations are as follows.

OBW8B-002, 001 (OBG 8AW-8BW-S.P, Counter weight side)

ULTRASONIC INSPECTION

OBG SEGMENT 11AE

ABF Report No: UT-11E-006

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern “D” UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the weld between edge panel and deck panel OBG segment 11AE. The weld designations are as follows.

CA081-004 (OBG 11AE-D.P to E.P, Cross beam side)

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant	Quality Assurance Inspector
----------------------	-----------------	-----------------------------

Reviewed By:	Dawson,Paul	QA Reviewer
---------------------	-------------	-------------