

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015308**Date Inspected:** 24-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Gao Zhi Chun**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Shailesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

This QA Inspector observed the following work in progress:

BAY 11: SMAW Process

This QA Inspector observed ZPMC qualified welding personnel identified as 040667, 041271 Perform Shielded Metal Arc Welding (SMAW) on Tower strut. Joint identified as WD1-STSA4-5-123M-1-27, 32 ZPMC CWI Identified as Yu Dong Ping, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2113, and WPS-B-T-4113-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 251194, 040655 Perform Shielded Metal Arc Welding (SMAW) on Tower strut. Joint identified as SD1-STSA4-5-131M-1-43, 37, ZPMC CWI Identified as Yu Dong Ping, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2113.

This QA Inspector observed ZPMC qualified welding personnel identified as 046769, 044551 Perform Shielded Metal Arc Welding (SMAW) on Tower strut. Joint identified as SD1-STSA4-5-139M-1-15, 16, 13, 14, ZPMC CWI Identified as Yu Dong Ping, The welding parameters as measured using QC's calibrated instrument appeared

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

to be in general compliance with WPS-B-T-2113.

SMAW Process, Repair Welding.

This QA Inspector observed ZPMC qualified welding personnel identified as 044541, Perform Shielded Metal Arc Welding (SMAW) on Tower strut. Joint identified as ND1-STSA4-6-139M-2-73B, ZPMC QC Identified as Liu Dao Feng, with temporary welding repair report. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-485-SMAW-2G (2F)-FCM-Repair-1. For more information see below attach photo number 1.

This QA Inspector observed ZPMC qualified welding personnel identified as 046709, Perform Shielded Metal Arc Welding (SMAW) on Interior splice plate. Joint identified as ESD1-SPSA5-7-4B. ZPMC QC Identified as Xu Jie, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 040611, Perform Shielded Metal Arc Welding (SMAW) on Interior splice plate. Joint identified as ESD1-SPSA5-20-2B. ZPMC QC Identified as Xu Jie, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 046704, Perform Shielded Metal Arc Welding (SMAW) on Interior splice plate. Joint identified as WSD1-SPSA5-12-1B. ZPMC QC Identified as Xu Jie, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 040614, Perform Shielded Metal Arc Welding (SMAW) on Interior splice plate. Joint identified as ESD1-SPSA5-12-3B. ZPMC QC Identified as Xu Jie, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

FCAW Process:

This QA Inspector observed ZPMC qualified welding personnel identified as 049220, Perform Flux Core Arc Welding (FCAW) on West Tower lift 4 Fit Lug near 127M double diaphragm. Joint identified as WSTL4-2G/L-113, 114. ZPMC QC Identified as Ma Qian Hi, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2332-Tc-P4-F and WPS-B-T-4332-Tc-P4-F. For more information see below attach photo number 2.

BAY 10: SMAW Process:

This QA Inspector observed ZPMC qualified welding personnel identified as 044511, Perform Shielded Metal Arc Welding (SMAW) on Interior splice plate. Joint identified as NSD1-SPSA5-6-4B, ZPMC QC Identified as Lu Wei Chao, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 050266, Perform Shielded Metal Arc Welding (SMAW) on Interior splice plate. Joint identified as SSD1-SPSA5-6-2A, ZPMC QC Identified as Lu Wei

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

Chao, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 052493, Perform Shielded Metal Arc Welding (SMAW) on Interior splice plate. Joint identified as SSD1-SPSA5-13-2A, ZPMC QC Identified as Lu Wei Chao, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

SMAW Process:

This QA Inspector observed ZPMC qualified welding personnel identified as 052930, Perform Shielded Metal Arc Welding (SMAW) on Façade seal angle. Joint identified as SD1-SFSA4-177-1~16, ZPMC QC Identified as Yu Zhi Lai. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-P-2111.

This QA Inspector observed ZPMC qualified welding personnel identified as 053829, Perform Shielded Metal Arc Welding (SMAW) on Façade seal angle. Joint identified as SD1-SFSA4-296-1~12, ZPMC QC Identified as Yu Zhi Lai. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-P-2111.

FCAW Process:

This QA Inspector observed ZPMC qualified welding personnel identified as 053116, Perform Flux Core Arc Welding (FCAW) on Façade channel. Joint identified as SD1-SFSA4-29A/B-1, 2. ZPMC QC Identified as Yu Zhi Lai, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2132.

This QA Inspector observed ZPMC qualified welding personnel identified as 052075, Perform Flux Core Arc Welding (FCAW) on Façade channel. Joint identified as SD1-SFSA4-6B/B-1, 2. ZPMC QC Identified as Yu Zhi Lai, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2132.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 4 of 4)



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Michael Ng Phone: 15921845703, who represents the Office of Structural Materials for your project.

Inspected By: Gaikwad,Shailesh

Quality Assurance Inspector

Reviewed By: Clifford,William

QA Reviewer