

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021396**Date Inspected:** 30-Jan-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Geng Wei**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Larry Viars was present during the times noted above for observations relative to the work being performed.

Bay 14-

This QA Inspector observed the following work in progress: Shielded Metal Arc Welding (SMAW) of OBG Segment 14E weld, 3019D-1-323. ZPMC welders were identified as 066418. ZPMC QC was identified as Guo Xing Hui. The welding appeared to be in conformance with Critical Weld Repair (CWR) report B-CWR 2678 and welding procedure specification, WPS-345-SMAW-2G(2F)-FCM-Repair.

Flux Cored Arc Welding (FCAW) of OBG Segment 14E weld SEG3019BB-047. ZPMC welder was identified as 066763. ZPMC QC was identified as Xie Ming Feng. ZPMC CWI was identified as Geng Wei. The welding appeared to be in conformance ZPMC with welding procedure specification, WPS-B-T-2233-ESAB.

Flux Cored Arc Welding (FCAW) of OBG Segment 14E weld SEG3019BB-069. ZPMC welder was identified as 067877. ZPMC QC was identified as Xie Ming Feng. ZPMC CWI was identified as Geng Wei. The welding appeared to be in conformance ZPMC with welding procedure specification, WPS-B-T-2233-ESAB.

Flux Cored Arc Welding (FCAW) of OBG Segment 14E weld SEG3019BB-009. ZPMC welder was identified as 067079. ZPMC QC was identified as Xie Ming Feng. ZPMC CWI was identified as Geng Wei. The welding appeared to be in conformance with ZPMC welding procedure specification, WPS-B-T-2233-ESAB.

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

**Summary of Conversations:**

Only general conversation between QA and QC occurred this date.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150 0042 2372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Viars,Larry	Quality Assurance Inspector
----------------------	-------------	-----------------------------

---

<b>Reviewed By:</b>	McClendon,Timothy	QA Reviewer
---------------------	-------------------	-------------