

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024543**Date Inspected:** 24-May-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	OBG	

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Vikram Singh was present during the times noted above for observations relative to the work being performed at ZPMC.

NDT

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 09247.

Ultrasonic Testing (UT)

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an UT report for this date. The member is identified as 13AE & 13CE. The weld designations reviewed is as follows:

SEG3007S-147, 151, 155, 159, 163, 190, 194, 198

VP3008-001-011, 012

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 09248.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Magnetic Particle Testing (MT)

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date. The member is identified as 13AW. The weld designations reviewed is as follows:

SEG3013V-015~018, 021~024, 398, 399, 401, 402, 404, 405, 407, 408, 126, 127, 337, 338

SEG3013W-160~163, 166~169, 172, 173, 175, 176, 178, 179, 181, 182, 012, 013, 140, 141

Ultrasonic Testing (UT)

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an UT report for this date. The member is identified as 13AW. The weld designations reviewed is as follows:

SEG3013AH-021, 020, 023, 035

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey-15000026784, who represents the Office of Structural Materials for your project.

Inspected By:	Singh, Vikram	Quality Assurance Inspector
----------------------	---------------	-----------------------------

Reviewed By:	Riley, Ken	QA Reviewer
---------------------	------------	-------------