

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.9/14.3,0.0/1.6File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-000848**Date Inspected:** 11-Nov-2007**Project Name:** SAS Superstructure**OSM Arrival Time:** 600**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	plate verification	

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Dan Hernandez arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following.

Plate Material Storage Yard (production):

QA Inspector received plate material list for batch #35 and #33. The following 52 out of 53 plates were observed for batch 35, production plate list No. 2349-2358 and 2360-2401. Batch #33 had 1 plate requiring verification, plate # 2307. The plates were observed for their general condition and markings. The Plate material thicknesses range from 12mm to 25mm. The plates were designated as A709M-345T2, A709M-345T2-X, A709M-345F2-X and A709M-345T2-X-S. Batch plate lists were received from American Bridge/Fluor (ABF) and were accompanied with material test reports (MTR's). QA Inspector assigned lot number L30-136-07 to these 52 plates of batch 35 and L30-137-07 to plate 2307 of batch #33. QA Inspector was accompanied to the ZPMC material storage yard by ZPMC Quality Control Mr. Sun Bo.

Summary of Conversations:

As identified within the contents of this report.

Plate verification was placed on hold due to rain.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
----------------------	---------------	-----------------------------

Reviewed By:	Cuellar,Robert	QA Reviewer
---------------------	----------------	-------------
