

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-001372**Date Inspected:** 31-Jan-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1830**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 630**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

<b>CWI Name:</b>	NA	<b>CWI Present:</b>	Yes	No
<b>Inspected CWI report:</b>	Yes No N/A	<b>Rod Oven in Use:</b>	Yes No N/A	
<b>Electrode to specification:</b>	Yes No N/A	<b>Weld Procedures Followed:</b>	Yes No N/A	
<b>Qualified Welders:</b>	Yes No N/A	<b>Verified Joint Fit-up:</b>	Yes No N/A	
<b>Approved Drawings:</b>	Yes No N/A	<b>Approved WPS:</b>	Yes No N/A	
		<b>Delayed / Cancelled:</b>	Yes No N/A	
<b>Bridge No:</b>	34-0006	<b>Component:</b>	114M Mockup	

**Summary of Items Observed:**

Caltrans Quality Assurance (QA) Inspector, Mike Hasler was present to observe the fitup, welding and related activities associated with the fabricating of Caltrans Mock-up, 77M, 89M, 114M and U-Rib Trial Assembly, for the San Francisco Oakland Bay Self Anchored Suspension Bridge, at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

Item Description	WBS	Dwg No.	Status
1 114M Mockup	NA	NA	Work In Progress

114M (upper tower shaft) Mock-up: Caltrans QA Inspector observed ZPMC shop workers drilling splice connection holes at Skin Plate A. ZPMC performed the match drilling of Skin Plate A using a magnetic drill with an annular drill bit. The drilling of Skin Plate A appeared to be in general conformance with the Tower Splice Mock-up Fabrication Procedure. Following digital picture illustrates the drilling in progress at the work station.

---


---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---



## Summary of Conversations:

ZPMC Quality Control (QC) Inspector, Mr. Ley Tao stated that ZPMC would be welding in the Tower Shop on 89M Mockup and perform the drilling of splice connection holes on 114M Mockup in Bay 2. Caltrans QA Inspector, Mr. Dan Hernandez and Mr. Paul Stovall stated that they would performed welding observations at the 89M Mockup.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Hasler, Mike	Quality Assurance Inspector
<b>Reviewed By:</b>	Cuellar, Robert	QA Reviewer

---