

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-001834**Date Inspected:** 19-Mar-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1800**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 630**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

| | | | | |
|------------------------------------|------------|----------------------------------|---------------------|----|
| CWI Name: | N/A | CWI Present: | Yes | No |
| Inspected CWI report: | Yes No N/A | Rod Oven in Use: | Yes No N/A | |
| Electrode to specification: | Yes No N/A | Weld Procedures Followed: | Yes No N/A | |
| Qualified Welders: | Yes No N/A | Verified Joint Fit-up: | Yes No N/A | |
| Approved Drawings: | Yes No N/A | Approved WPS: | Yes No N/A | |
| | | Delayed / Cancelled: | Yes No N/A | |
| Bridge No: | 34-0006 | Component: | Macro Etched Sample | |

Summary of Items Observed:

On this date, Caltrans Office of Structural Materials (OSM), Quality Assurance (QA) Inspector, David A. Smith was present for the observations related the following;

During the evening shift this Caltrans QA Inspector did photograph four lots of Macro Etched Samples and are as follows, Deck Panel DP-026-001/DP-030-001, DP-028-001/DP-071-001, DP-032-001/DP-040-001 and DP-072-001/DP-070-001.

These photographs were down loaded and placed in the Shared Docs on Team China Server for review.

Summary of Conversations:

There were no pertinent conversations pertaining to the project during this shift.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By: Smith, David

Quality Assurance Inspector

Reviewed By: Hager, Craig

QA Reviewer