

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 70.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002334**Date Inspected:** 10-Mar-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 830**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1930**Contractor:** Japan Steel Works**Location:** Muroran, Japan

<b>CWI Name:</b>	Chung Kuan and MaKhmun Asha			<b>CWI Present:</b>	<b>Yes</b>	<b>No</b>	
<b>Inspected CWI report:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Rod Oven in Use:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>
<b>Electrode to specification:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Weld Procedures Followed:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>
<b>Qualified Welders:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Verified Joint Fit-up:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>
<b>Approved Drawings:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Approved WPS:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>
				<b>Delayed / Cancelled:</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>
<b>Bridge No:</b>	34-0006			<b>Component:</b>	PQR test plate		

**Summary of Items Observed:**

Caltrans Quality Assurance Inspector (QAI) representative Mr. Wai Pau, travel to Japan Steel Works (JSW) Muroran plant to verify a test plate fit up for AWS D1.5 standard PQR qualification welding test. The number of PQR qualification welding test is SJ-2942-WP-5 (test plate SW-4-1). The weld joint design used butt joint, single-V-groove weld with 20mm x 75mm backing bar. Based on Caltrans QA observation, no discrepancies were noted.

QAI Mr. Wai Pau with Mr. Danny Reyes reviewed contract documents and Nikko Inspection Services (NIS) non destructive testing procedures for the project. After review of the contract documents, the QAI inspectors toured the facility with JSW personnel Mr. Yoshihiro Itoh. The tour included the casting facility, machine shop, welding fabrication facility and nondestructive testing area. The reason for this tour is Mr. Danny Reyes is new inspector assigned on this project. Based on Caltrans QA observation, no discrepancies were noted.

**Summary of Conversations:**

As Note within the report above.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Venkatesh Iyer (858)697-6363, who represents the Office of Structural Materials for your project.

**Inspected By:** Pau, Wai

Quality Assurance Inspector

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

**Reviewed By:** Brasel,Ron

QA Reviewer