

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002533**Date Inspected:** 29-Jan-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1800**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhu Zhong Hai**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower Mock-Ups**Summary of Items Observed:**

The Caltrans Quality Assurance (QA) Inspector, M. Paul Stovall, was present at Zhenhua Port Machinery Company, (Z. P. M. C.), on Changxing Island, Shanghai, China for the purpose of monitoring the fabrication of the SAS/San Francisco/Oakland Bay Bridge.

The QA Inspectors received the fabrication procedures that will be used fabricate and inspect the Closed Rib, Orthotropic Box Girders (OBG) Deck Panels.

OBG Pre-Assembly Area, Bay 1

The QA Inspector observed ZPMC personnel at the 114-meter Mock-Up complete the drilling of bolt holes, with the template removed.

At the 89-meter Mock-Up, the QA Inspector observed Z. P. M. C. personnel start building scaffolding around the Mock-Up to continue doing work.

This is the extent of the work performed.

Summary of Conversations:

The QA Inspector had no substantial conversations.

Comments

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Stovall,Paul	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer
