

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002745**Date Inspected:** 23-May-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Wang Sei Fa**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Deck Panel Repairs**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector was present during the times noted above for observations relative to the work being performed.

**Bay 3 – New Tower Building**

This QA Inspector randomly observed ZPMC welding and quality control personnel performing inspection, grinding, and Flux Core Arc Welding (FCAW) repairs of Orthotropic Box Girder (OBG) deck panel Partial Joint Penetration (PJP) welds. The deck panels in repair process are designated as: DP074-001, DP038-001, DP005-001, DP020-001, DP077-001, DP040-001, DP018-002.

The deck panels located in Tower Shop Bay #3 are designated as:

DP041-001 DP037-001 DP038-001 DP080-001 DP038-002 DP075-001  
DP039-001 DP074-001 DP042-002 DP005-001 DP015-001 DP051-001  
DP056-001 DP014-001 DP002-002 DP058-001 DP053-001 DP049-001  
DP055-001 DP020-001 DP077-001 DP078-001 DP040-001 DP001-001  
DP014-002 DP063-001 DP006-001 DP002-001 DP017-001 DP059-001  
DP018-002 DP008-001


This QA Inspector reviewed the contract files and tracking logs for the Magnetic Particle Testing (MT), Ultrasonic Testing (UT), Welding Procedure Specifications (WPS), Procedure Qualification Records (PQR), and QC Inspector records for the deck panel repairs to date.

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---



## Summary of Conversations:

No relevant conversations.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

---

**Inspected By:** Clifford, William

Quality Assurance Inspector

---

**Reviewed By:** Cuellar, Robert

QA Reviewer