

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 13.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-003327**Date Inspected:** 25-Jul-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Oregon Iron Works Clackamas, Or.**Location:** Clackamas, Oregon**CWI Name:** Gary Mundt**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Hinge K components**Summary of Items Observed:**

On this date, Caltrans Quality Assurance Inspector (QA) Danny C. White (B89) was present at Oregon Iron Works (OIW) for the purpose of monitoring fabrication operations of the Hinge K Pipe Beam at the OIW fabrication and welding shop in Clackamas, Oregon.

The QA Inspector performed random observations in the fabrication and machine shops at OIW. The QA Inspector observed that the 30 foot planer mill in the fabrication shop (Bay #1) was machining on the Base-plate component marked a110 for this job. The QA Inspector performed a random check of this component and the machining performed appears to be in conformance with contract documents.

Summary of Conversations:

After the end of the QA Inspectors shift, Quality Control (QC) Inspector Mr. Gary Mundt informed the QA Inspector by telephone that OIW has started welder qualifications on swing shift and that Mr. Mundt would be the third party observing these tests.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ryan Smith, (858) 232-6799, who represents the Office of Structural Materials for your project.

Inspected By: White, Danny

Quality Assurance Inspector

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Reviewed By: Wright,Mark

QA Reviewer