

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-004165**Date Inspected:** 09-Oct-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	OBG	

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Larry Viars was present to perform Ultrasonic Testing (UT) of Orthotropic Box Girder (OBG) components, for the San Francisco Oakland Bay Self Anchored Suspension Bridge, at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

Heavy Tower Bay 3:

This Quality Assurance (QA) inspector arrived at ZPMC in Shanghai China for observation of Orthotropic Bridge Girders (OBG) and Self Anchored Suspension (SAS) Bridge. This QA inspector received notification from day shift task leader to perform conventional Ultrasonic (A scan) Inspection for tack welds on 564-001 deck panel. The above mentioned deck panel was previously removed from service and used to develop an ultrasonic testing technique for evaluating cracking located in U-rib Partial Joint penetration welds. Testing was for informational purposes only.

No other activities observed.

Summary of Conversations:

Only general conversations between Caltrans QA and QC occurred this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Peter Dautermann 150 0219 9593, who represents the Office of Structural

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Materials for your project.

Inspected By:	Viars,Larry	Quality Assurance Inspector
----------------------	-------------	-----------------------------

Reviewed By:	Wright,Mark	QA Reviewer
---------------------	-------------	-------------