

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-006246**Date Inspected:** 09-Apr-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhao Chen Sun**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG components**Summary of Items Observed:**

On the date CALTRANS OSM Quality Assurance (QA) Inspector, Dilip Chakrabarti was present during the times noted above for observations relative to the work being performed.

Bay# 6-OBG Assembly

This QA Inspector randomly observed the following work in progress:

Magnetic Particle Testing:

For Green Tag:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6028 MT report on this date.

The member and the weld designations are as follows:

Sl #	Section #	Weld #	Green Tag #	Location
1.	SP 638-001	041	006020	11 DE
2.	BP 507-001	036	006376	11 DW
3.	SP 745-001	001	006019	11 DW
4.	SP 503-001	063	006018	11 BW
5.	SP 785-001	023	006378	11 DW
6.	BP 107-001	007,008,010,012	006025	11 CW
7.	SP 559-001	001	006377	11 DE

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

- 8. SP 784-001 052 006373 11 DW
- 9. SP 596-001 001 006374 11 BE
- 10. SP 740-001 013,014,015,017 006380 11 AW
- 11. SP 785-001 038 006371 11 DW
- 12. SP 558-001 050 006372 11 DE
- 13. SP 639-001 047 006375 11 DE

Bay# 6-Tower Assembly

This QA Inspector randomly observed the following work in progress:

FCAW Process:

Welding of weld joints# 10&38 located on PCMK WD1 CBSA3-1-2. Welder is identified as 019609. ZPMC QC is identified as Zhong Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2133.

Welding of weld joints# 10&38 located on PCMK WD1 CBSA3-1-4. Welder is identified as 019006. ZPMC QC is identified as Zhong Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2133.

Welding of weld joints# 9&41 located on PCMK WD1 CBSA3-1-2. Welder is identified as 053609. ZPMC QC is identified as Zhong Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2133.

Welding of weld joints# 9&41 located on PCMK WD1 CBSA3-1-4. Welder is identified as 053609. ZPMC QC is identified as Zhong Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2133.

Bay # 7-OBG Assembly:

This QA Inspector randomly observed the following work in progress:

FCAW Process:

Welding of weld joints# 15&16 located on PCMK SP 502-001. Welder is identified as 054459. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132- 3.

Welding of weld joints# 23&24 located on PCMK SP 502-001. Welder is identified as 205774. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132- 3.

Welding of weld joints# 27&28 located on PCMK SP 502-001. Welder is identified as 062447. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132- 3.

Unless otherwise noted, all work observed on this date appeared to be generally comply with applicable contract

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

document

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Chakrabarti,Dilip Kumar	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
