

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
 690 Walnut Ave. St. 150
 Vallejo, CA 94592-1133
 (707) 649-5453
 (707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-006677**Date Inspected:** 07-May-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Huang Wen pang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG FB, LD / TOWER CSD**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, D.Sukanthan was present during the time noted above for observations relative to the work being performed.

OBG # BAY 3

This QA inspector performed Magnetic Particle Test of approximately 15% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an Magnetic Particle Test report for this date. The member is identified as Floor Beam / Longitudinal Diaphragm. The weld designations reviewed are as follows:

(FB040-003-088,071,058,060,065,148,136,137,133,132,028,029,093,127) Side-B.

(FB040-003-134,135,098,099,115,116,073,070,146) Side-A, Green Tag # 006680.

(LD003-035-011) Green Tag # 007491.

(LD003-037-011) Green Tag # 007480.

(LD003-038-011) Green Tag # 007485.

(LD004-032-011) Green Tag # 007484.

(LD004-036-011) Green Tag # 007487.

(LD004-037-011) Green Tag # 007483.

(LD011-011-011) Green Tag # 007482.

(LD011-012-011) Green Tag # 007473.

(LD020-006-011) Green Tag # 007475.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

(LD022-004-011) Green Tag # 007486.
(LD001-023-011) Green Tag # 007490.
(LD001-025-011) Green Tag # 007476.
(LD001-026-011) Green Tag # 007488.
(LD003-033-011) Green Tag # 007481.
(LD012-011-011) Green Tag # 007474.
(LD012-012-011) Green Tag # 007477.
(LD013-008-011) Green Tag # 007479.
(LD014-007-011) Green Tag # 007472.
(LD014-008-011) Green Tag # 007478.
(LD019-005-011) Green Tag # 007489.

TOWER # BAY 10

This QA inspector performed Ultrasonic Test of approximately 10% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an Ultrasonic Test report for this date. The member is identified as Corner Diagonal Stiffener. The weld designations reviewed are as follows:

(SSD1-TL5 K/L-020,022,024,025,026,047,049,052,053,056,057) Side – A.

This QA Inspector randomly observed the following work in progress:

OBG # BAY 3

Submerged Arc Welding Process:

Welding of weld joint –021 located on PCMK FB009-038. Welder is identified as 050502. ZPMC QC is identified as Huang Wen pang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2221-B-L2C-S2.

Welding of weld joint –079,101 located on PCMK FB024-011. Welder is identified as 044780. ZPMC QC is identified as Huang Wen pang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2221-B-L2C-S2.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant Conversation

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Sukanthan,Dhanasingh	Quality Assurance Inspector
----------------------	----------------------	-----------------------------

Reviewed By:	Prue,Erik	QA Reviewer
---------------------	-----------	-------------