

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-007909**Date Inspected:** 19-Jul-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

<b>CWI Name:</b>	N/A	<b>CWI Present:</b>	<b>Yes</b>	<b>No</b>
<b>Inspected CWI report:</b>	<b>Yes</b> <b>No</b> <b>N/A</b>	<b>Rod Oven in Use:</b>	<b>Yes</b>	<b>No</b> <b>N/A</b>
<b>Electrode to specification:</b>	<b>Yes</b> <b>No</b> <b>N/A</b>	<b>Weld Procedures Followed:</b>	<b>Yes</b>	<b>No</b> <b>N/A</b>
<b>Qualified Welders:</b>	<b>Yes</b> <b>No</b> <b>N/A</b>	<b>Verified Joint Fit-up:</b>	<b>Yes</b>	<b>No</b> <b>N/A</b>
<b>Approved Drawings:</b>	<b>Yes</b> <b>No</b> <b>N/A</b>	<b>Approved WPS:</b>	<b>Yes</b>	<b>No</b> <b>N/A</b>
		<b>Delayed / Cancelled:</b>	<b>Yes</b>	<b>No</b> <b>N/A</b>
<b>Bridge No:</b>	34-0006	<b>Component:</b>	OBG Floorbeams	

**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Steve Hall was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

## OBG assembly bay 2

This QA received ZPMC Non Destructive Testing (NDT) notification No. 003735 and performed Ultrasonic Testing (UT) of approximately 10% of the welds previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA generated a UT report for this date. The weld designation is as follows: FB023-008-125, 126 and 127, SSD13-PP091-137, FB023-009-125, 126 and 127, FB019-006-126 and 127.

This QA received ZPMC Non Destructive Testing (NDT) notification No. 003736 and performed Ultrasonic Testing (UT) of approximately 10% of the welds previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA generated a UT report for this date. The weld designation is as follows: FB010-030-045.

## OBG assembly bay 3

This QA received ZPMC Non Destructive Testing (NDT) notification No. 003735 and performed Ultrasonic Testing (UT) of approximately 10% of the welds previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA generated a UT report for this date. The weld designation is as follows: FB003-194-008, FB003-190-008, SSD13-PP097-137 and SSD13-PP096-137.

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

**Summary of Conversations:**

Only general conversation was held between QA and QC concerning this project.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (15000422372), who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Hall,Steven	Quality Assurance Inspector
----------------------	-------------	-----------------------------

---

<b>Reviewed By:</b>	Prue,Erik	QA Reviewer
---------------------	-----------	-------------