

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 70.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-007921**Date Inspected:** 18-Jul-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 730**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1600**Contractor:** Japan Steel Works**Location:** Muroran, Japan

CWI Name:	Chung Fu Kuan		
Inspected CWI report:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A

CWI Present:	Yes	No	
Rod Oven in Use:	Yes	No	N/A
Weld Procedures Followed:	Yes	No	N/A
Verified Joint Fit-up:	Yes	No	N/A
Approved WPS:	Yes	No	N/A
Delayed / Cancelled:	Yes	No	N/A
Component:	Tower, Jacking and Deviation Saddles		

Bridge No: 34-0006**Summary of Items Observed:**

On this date, 7/18/09, Caltrans OSM Quality Assurance Inspector (QAI) Mike Brcic was present during the times noted above for observations relative to the work being performed on cast sections in Foundry and associated built up plate sections in the Fabrication shop #4 at Japan Steel Works (JSW), Muroran, Japan.

WEST DEVIATION SADDLES

W2W1 - On this day Caltrans OSM/Mets QA Inspector performed Dry MT of AWS welds, see Magnetic Particle Test Report, TL-6028, dated 7/18/2009 for equipment, process and results.

W2W2 - Idle, no activity observed on this day.

W2W3 - Idle, no activity observed on this day.

TOWER SADDLES

T1-3 - This QA Inspector observed joint 9Y-12L-1 of base plate, 9-4, was being welded by T.Watanabe 08-5153 by FCAW using 1.6mm consumable TM55 weld wire, and procedure SJ-3012-3, in Fabrication Shop #4. These functions were being monitored by QC CWI Mr. Chung Fu Kuan on a random basis.

Unless otherwise noted, all observations reported on this date appeared to be in general compliance with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Summary of Conversations:

No significant conversations to report on this day.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy, 1(510)385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Brcic,Michael	Quality Assurance Inspector
Reviewed By:	Peterson,Art	QA Reviewer
