

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-008001**Date Inspected:** 02-Jul-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lui wei wei**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, D.Sukanthan was present during the time noted above for observations relative to the work being performed.

OBG # BAY 02

This QA inspector performed Ultrasonic Test of approximately 10% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an Ultrasonic Test report for this date. The member is identified as Floor Beam. The weld designations reviewed are as follows:

(FB027-010-146)

OBG # BAY 03

This QA inspector performed Ultrasonic Test of approximately 10% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an Ultrasonic Test report for this date. The member is identified as Floor Beam. The weld designations reviewed are as follows:

(FB015-044-043)

(FB010-035-043)

(FB015-042-045) Green Tag # 009619

(FB016-046-045) Green Tag # 009617

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

OBG # BAY 12

This QA inspector performed Ultrasonic Test of approximately 10% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an Ultrasonic Test report for this date. The member is identified as Deck Plate. The weld designations reviewed are as follows:

(DP3040-001-017)

(DP3041-001-022)

(DP3045-001-027)

(DP3047-001-022)

(DP3048-001-017)

This QA Inspector randomly observed the following work in progress:

OBG # BAY 03

Flux Cored Arc Welding Process:

Welding of weld joint –132 located on PCMK SSD19A-PP095. Welder is identified as 044830. ZPMC QC is identified as Lui wei wei. The welding variables recorded by QC appeared to comply with the WPS-B-T-2233-TC-U4b-F.

Welding of weld joint –133 located on PCMK FB003-199. Welder is identified as 044830. ZPMC QC is identified as Lui wei wei. The welding variables recorded by QC appeared to comply with the WPS-B-T-2233-TC-U4b-F.

OBG # BAY 06

Flux Cored Arc Welding Process:

Welding of weld joint –025 located on PCMK FB205-019. Welder is identified as 058174. ZPMC QC is identified as Xu xian ping. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-B-U2-F-1.

Welding of weld joint –158 located on PCMK CB202G-019. Welder is identified as 019006. ZPMC QC is identified as Li yang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2133.

Submerged Arc Welding Process:

Welding of weld joint –002 located on PCMK CB202F-009. Welder is identified as 046830. ZPMC QC is identified as Li yang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2221-B-L2C-S-2.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant Conversation

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-00422372, who represents the Office of Structural Materials for your project.

Inspected By:	Sukanthan,Dhanasingh	Quality Assurance Inspector
----------------------	----------------------	-----------------------------

Reviewed By:	Prue,Erik	QA Reviewer
---------------------	-----------	-------------