

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-008344**Date Inspected:** 07-Jul-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	Zhu Zheng Hai & Shen Fu You			CWI Present:	Yes	No	
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006			Component:	OBG Bays 13 & 14		

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Rory O'Kane was present during the time noted above for observations relative to the work being performed.

This QA Inspector randomly observed the following work in progress:

OBG - BAY No. 13

Shielded Metal Arc Welding Process:

Welding of weld joint SEG043A-009 located on OBG Segment 8AW. Welder is identified as 067656. ZPMC QC is identified as Zhu Zheng Hai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2214-TC-U4b-FMC-1.

Welding of weld joint EP72A-001-030 located on OBG Segment 8AW. Welder is identified as 067704. ZPMC QC is identified as Zhu Zheng Hai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2214-TC-U4b-FMC-1.

OBG - BAY No. 14

Flux Cored Arc Welding Process:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Welding of weld joint SSD14-PP55-242 located on OBG Segment 7CW. Welder is identified as 045175. ZPMC QC is identified as Shen Fu You. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-TC-U4b-F.

Visual Inspection - General

This QA Inspector observed unapproved Base Metal Repairs on OBG Segment designated as 7CE and completed a survey to determine the approximate extent of the repairs. See submitted Incident Report for details.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, who represents the Office of Structural Materials for your project.

Inspected By:	O'Kane,Rory	Quality Assurance Inspector
----------------------	-------------	-----------------------------

Reviewed By:	Carreon,Albert	QA Reviewer
---------------------	----------------	-------------