

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-008468**Date Inspected:** 10-May-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Zhi jiang/ Li Xin Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Hiranch Patel, was present during the times noted above for observations relative to the work being performed.

Bay#3

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member is identified as OBG Components. The weld designations reviewed are as follows:

-(FB024-011-078, 081, 101)

-(FB019-009-078, 079, 081, 101)

-(FB027-012-078, 079, 081, 101)

-(FB009-028-045)

Bay#3

This QA inspector observed that all the required NDT work is completed and accepted by ZPMC and CT. This QA inspector issued the green tag for these components. The member is identified as OBG Components. The weld designations reviewed are as follows:

-(FB010-022) Green Tag# 006685

-(FB009-024) Green Tag# 006686

-(FB016-035) Green Tag# 006687

Bay#2

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA inspector observed the following work in progress:

FCAW welding of weld joint FB028-010-125, 126, 127, 128 located on FB028-010. Welder is identified as 045143 (3F). ZPMC QC is identified as Geng Wei. The welding variables recorded by QC appeared to comply with the Applicable WPS.

FCAW welding of weld joint FB020-006-125, 126, 127, 128 located on FB020-006. Welder is identified as 062708 (3F). ZPMC QC is identified as Geng Wei. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Unless otherwise noted, all observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Patel,Hiranch	Quality Assurance Inspector
Reviewed By:	Prue,Erik	QA Reviewer
