

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-009343**Date Inspected:** 25-Mar-2009**Project Name:** SAS Superstructure**OSM Arrival Time:****Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:****Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Hu Wei Jing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Chandrakumar.S, was present during the times noted above for observations relative to the work being performed.

BAY#19

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an MT report for this date. The member is identified as Bottom Plate. The weld designations reviewed as follows:

BP025-004-04,06,09,15,19,46,47,48,50,53. Green Tag no-005413.

SEG#1BW

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an MT report for this date. The member is identified as Segment(1BW). The weld designations reviewed as follows:

FB057-001-26,27,29,30.

FB055-001-35,36,29,30.

FB067-001-62,64,61,62.

FB059-002-03,75,76,83,77.

BAY#19

@On going FCAW & SMAW Welding of Weld Joint 1G-001 Located on BP0025-005 Welder no identified as 062739 & 062816 and The welding variables recorded by QC ZPMC to comply with the WPS-B-T-2231-B-U2-F

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

& WPS-B-T-2221-B-L2C-S-2.

Unless otherwise noted, all observed on this date appeared to generally comply with applicable contract documents

Summary of Conversations:

No Relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang-150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Chadra	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
