

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-011350**Date Inspected:** 08-Jan-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Lu Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Orthotropic Box Girder (OBG)**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA), Vibin Kumar Selvanayaham, was present during the times noted above for observations relative to the work being performed.

Bay 13

This QA inspector observed ZPMC qualified welding personnel identified as 058551 perform Flux Cored Arc Welding (FCAW) welding on Segment 11CW, weld joint identified as SSD14A-PP103-226 & 256. ZPMC QC is identified as Mr. Guo Xing Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2133-Tc-U4b-F.

This QA inspector observed ZPMC qualified welding personnel identified as 051356 perform FCAW welding on Segment 11CW, weld joint identified as SSD14-PP103-227 & 257. ZPMC QC is identified as Mr. Guo Xing Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2133-Tc-U4b-F.

This QA inspector observed ZPMC qualified welding personnel identified as 050988 perform FCAW welding on Segment 11CW, weld joint identified as SSD29-PP101.5-099~132. ZPMC QC is identified as Mr. Guo Xing Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2133-F.

This QA inspector observed ZPMC qualified welding personnel identified as 048038 perform FCAW welding on

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Segment 11CE, weld joint identified as SEG065*-010. ZPMC QC is identified as Mr. Guo Xing Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-213(3)1-T-2.

Bay 14

This QA inspector observed ZPMC qualified welding personnel identified as 044779 & 050242 FCAW Welding on Corner Assembly, weld joint identified as CA094-003. ZPMC QC is identified as Mr. Zhong Guo Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-Tc-U4b-F.

This QA inspector observed ZPMC qualified welding personnel identified as 202122 FCAW Welding on Segment 11DE, weld joint identified as SEG071A-025 (SP684A+SP744A). ZPMC QC is identified as Mr. Zhong Guo Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2231-B-U2-F.

Bay 19

This QA inspector observed ZPMC qualified welding personnel identified as 062752 & 062788 perform FCAW welding on Suspender Bracket, weld joint identified as SB008-036-025, 31, 37, 43, 49, 55, 61 & 67. ZPMC QC is identified as Mr. Zhou Cheng. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-Tc-U4b-F.

This QA inspector observed ZPMC qualified welding personnel identified as 062763 & 062731 perform FCAW welding on Suspender Bracket, weld joint identified as SB008-040-025, 31, 37, 43, 49, 55, 61 & 67. ZPMC QC is identified as Mr. Zhou Cheng. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-Tc-U4b-F.

This QA inspector observed ZPMC qualified welding personnel identified as 062732 & 062761 perform FCAW welding on Suspender Bracket, weld joint identified as SB008-038-025, 31, 37, 43, 49, 55, 61 & 67. ZPMC QC is identified as Mr. Zhou Cheng. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-Tc-U4b-F.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang - 15000422372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Kumar,Vibin	Quality Assurance Inspector
----------------------	-------------	-----------------------------

Reviewed By:	Hall,Steven	QA Reviewer
---------------------	-------------	-------------