

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-011756**Date Inspected:** 31-Jan-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhang Sheng Jun**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

Trial Assembly:

Notification No: 005157.

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT reports for this date. The members are identified as OBG Components (Bike Path). The weld designations reviewed are as follows:

- 1) PP35-BK001-016 – 005, 006, 007 & 009.
- 2) PP37-BK001-019 – 005, 006, 007 & 009.
- 3) PP39-BK001-020 – 005, 006, 007 & 009.
- 4) PP41-BK001-021 – 005, 006, 007 & 009.
- 5) PP45-BK001-023 – 005, 006 & 007.

Notification No / Request No: 01312010-3

---

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

This QA inspector performed Magnetic Particle Testing (MT) of repaired area of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector has generated MT report for this date. The member(s) are identified as OBG components. The weld designations reviewed are as follows:

6BW-CA13 – 003.

Trial Assembly:

This QA Inspector observed the following work in progress:

Flux Cored Arc Welding (FCAW) of weld joint PP51-BP117-020 (for SEG 7BE). Welder is identified as 067949. ZPMC QC is identified as Zhang Sheng Jun. The welding variables recorded by QC appeared to comply with the Applicable WPS – WPS-B-T-2233-B-U2-F.

Shielded Metal Arc Welding (SMAW) of weld joint PP51-SP462-031 (for SEG 7BE). Welder is identified as 067829. ZPMC QC is identified as Zhang Sheng Jun. The welding variables recorded by QC appeared to comply with the Applicable WPS – WPS-B-T-3213-B-U3B.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### **Summary of Conversations:**

Only general conversation was held between QA and QC concerning this project.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Wadkar,Sailesh	Quality Assurance Inspector
<b>Reviewed By:</b>	Hall,Steven	QA Reviewer

---