

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015314**Date Inspected:** 24-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhu Feng**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

**TOWER JETTY**

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint # 18 located on East tower Lift-2 doubler plate to small doubler strut plate ESD1 – SA300C/F. Welder is identified as 202100. ZPMC Quality Control (QC) Inspector is identified Sun Zhi Wang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3212 – B – U2a – 2.

**BAY#10**

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint # 14 located on Façade Seal Angle SD1 – SFSA4 – 177. Welder is identified as 052930. ZPMC Quality Control (QC) Inspector is identified as Yu Zhi Lai. The welding variables recorded by QC appeared to comply with the WPS – B – P – 2111.

# WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

Weld joint # 2A located on Lift-5 Splice Plate Stiffener SSD1 – SPSA5 – 6. Welder is identified as 050200. ZPMC Quality Control (QC) Inspector is identified as Lu Wei Chao. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

Weld joint # 4B located on Lift-5 Splice Plate Stiffener NSD1 – SPSA5 – 6. Welder is identified as 044511. ZPMC Quality Control (QC) Inspector is identified as Lu Wei Chao. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

Weld joint # 12 located on Façade Seal Angle SD1 – SFSA4 – 296. Welder is identified as 053829. ZPMC Quality Control (QC) Inspector is identified as Yu Zhi Lai. The welding variables recorded by QC appeared to comply with the WPS – B – P – 2111. (See attached photo)

## BAY#11

This QA Inspector observed the following work in progress  
Shielded Metal Arc Welding (SMAW):

Weld joint # 4B located on Lift-5 Splice Plate Stiffener ESD1 – SPSA5 – 7. Welder is identified as 046709. ZPMC Quality Control (QC) Inspector is identified as Xu Jie. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1. (See attached photo)

Weld joint # 1B located on Lift-5 Splice Plate Stiffener WSD1 – SPSA5 – 12. Welder is identified as 046704. ZPMC Quality Control (QC) Inspector is identified as Xu Jie. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

Weld joint # 3B located on Lift-5 Splice Plate Stiffener ESD1 – SPSA5 – 12. Welder is identified as 040614. ZPMC Quality Control (QC) Inspector is identified as Xu Jie. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



---

---

# WELDING INSPECTION REPORT

( Continued Page 3 of 3 )

---

---

**Summary of Conversations:**

No Relevant Conversations.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Michael Ng - 15921845703, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Kumar,Sandeep	Quality Assurance Inspector
<b>Reviewed By:</b>	Clifford,William	QA Reviewer

---