

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1x.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015371**Date Inspected:** 29-Apr-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1300**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Jobsite Pier 7**CWI Name:****CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Lifts 5W & 6E**Summary of Items Observed:**

Post arrival inspection of OBG Lifts 5W and 6E.

By 0745 hours I met with Structures Construction and our METS counterparts to inspect OBG Lifts 5W Panel Points 33 to 36 and Lift 6E Panel Points 43 to 47. In both lifts, I inspected the inside of both lifts with Matt Bruce. There did not appear to be any damage due to transporting the OBG Lift segments from China.

**Summary of Conversations:****Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mohammad Fatemi (916) 813-3677, who represents the Office of Structural Materials for your project.

**Inspected By:** Gramlick, Jason

Quality Assurance Inspector

**Reviewed By:** Fatemi, Mohammad

QA Reviewer