

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-017214**Date Inspected:** 03-Oct-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance(QA) Inspector Mr. Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. The QA Inspector observed and/or found the following:

BAY # 14

ULTRASONIC TESTING

ZPMC NWIT: 06841

This QA Inspector performed Ultrasonic Testing (UT) of approximately 10% of the length previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an (UT) report on this date. The members are identified as OBG 13AE. The weld designations are as follows:

SEG3007AC-003

This QA Inspector randomly observed the following work in progress.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 645265 performing the Submerged Arc Welding process on weld 004 located at PCMK SEG3020A*. ABF QA Mr. Shao Jian Yuan was monitoring this welding operation. The welding variables recorded by QA appeared to comply with WPS-B-T-2221-B-U2c-s-2.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 044745 performing the Flux Cored Arc Welding process on weld 007 located at PCMK VP3016-001. ZPMC QC Mr. Lv Li Qing was monitoring this welding operation. The welding variables recorded by QA appeared to comply with WPS-345-FCAW-2G (2F)-Fcm-Repair. Weld repair report identified as B-WR15475.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 026737 performing the Submerged Arc Welding process on weld 006 located at PCMK SEG3020A*. ABF QA Mr. Shao Jian Yuan was monitoring this welding operation. The welding variables recorded by QA appeared to comply with WPS-B-T-2221-B-U2c-s-2.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 201981 performing the Flux Cored Arc Welding process on weld 005 located at PCMK SEG3014. ZPMC QC Mr. Li Yun was monitoring this welding operation. The welding variables recorded by QA appeared to comply with WPS-B-T-2131-B-u2-f.

This Quality Assurance (QA) Inspector observed ZPMC qualified welders 037996, 067589 and 066258 performing the Shielded Metal Arc Welding process on weld 001 located at PCMK OBE13C. ZPMC QC Mr. Zhong Guo Hui was monitoring this welding operation. The welding variables recorded by QA appeared to comply with WPS-B-P-2214-B-u2-f-1.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 044824 performing the Submerged Arc Welding process on weld 002 located at PCMK SEG3007. ABF QA Mr. Shao Jian Yuan was monitoring this welding operation. The welding variables recorded by QA appeared to comply with WPS-B-T-2221-B-U2c-s-2

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

| | | |
|----------------------|-----------------|-----------------------------|
| Inspected By: | Utekar,Shrikant | Quality Assurance Inspector |
|----------------------|-----------------|-----------------------------|

| | | |
|---------------------|--------------|-------------|
| Reviewed By: | Peterson,Art | QA Reviewer |
|---------------------|--------------|-------------|
