

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-019593**Date Inspected:** 06-Jan-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China**CWI Name:** See Below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector Brett W Rice was present during the times noted above for observations relative to the work being performed at ZPMC.

Bay 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Flux Cored Arc Welding (FCAW) process.

ZPMC QC is identified as Li Yan Hua.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

PCMK: SEG-3015-003

Weld No: Temporary lifting lugs

Welder: 207465

WPS-B-T-2132-ESAB

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Li Yan Hua.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

PCMK: SEG-3020AB

Weld No: 070, 072, 073

Welder: 067610

WPS-B-P-2114-FCM-1

PCMK: SEG-3020K

Weld No: 021

WR: 19831

Welder: 062757

WPS-345-SMAW-3G(3F)-Repair

ZPMC was observed on this date setting Deck panel SEG-3015-003 into place for fit up.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Photos please see ; Z:\Inspector Reports\B314 Rice

Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Rice,Brett	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer
