

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
 690 Walnut Ave. St. 150  
 Vallejo, CA 94592-1133  
 (707) 649-5453  
 (707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020506**Date Inspected:** 03-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

<b>CWI Name:</b>	Mr. Chen Xi	<b>CWI Present:</b>	Yes	No
<b>Inspected CWI report:</b>	Yes No N/A	<b>Rod Oven in Use:</b>	Yes No N/A	
<b>Electrode to specification:</b>	Yes No N/A	<b>Weld Procedures Followed:</b>	Yes No N/A	
<b>Qualified Welders:</b>	Yes No N/A	<b>Verified Joint Fit-up:</b>	Yes No N/A	
<b>Approved Drawings:</b>	Yes No N/A	<b>Approved WPS:</b>	Yes No N/A	
		<b>Delayed / Cancelled:</b>	Yes No N/A	
<b>Bridge No:</b>	34-0006	<b>Component:</b>	OBG	

**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Baskar Govindarajan, was present during the times noted above for observations relative to the work being performed.

**Bay #19**

During a random observation this QA inspector observed the following components for the Orthotropic Bridge Girder (OBG) in Bay 19;

Suspender Bracket SB 106E, SB 106W, SB 108E  
 Bike path BK004B-001

This QA observed that ZPMC was not performing any work on the above mentioned components during the time, this QA inspectors was present.

**Bay #28**

During a random observation this QA inspector observed the following components for the Orthotropic Bridge Girder (OBG) in Bay 28;

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

U Rib Splice plates:

SA3221A-031, SA3321-024, SA3321A -022, SA 7010B -002

This QA observed that ZPMC was not performing any work on the above mentioned components during the time, this QA inspectors was present.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

**Summary of Conversations:**

No relevent Conversations.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Thomas Hu (15002048250), who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Baskar, Govindarajan	Quality Assurance Inspector
<b>Reviewed By:</b>	Clifford, William	QA Reviewer

---