

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020801**Date Inspected:** 16-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhou Zhong Hai**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segments**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dan Hernandez was present during the times noted above to observe the fit up, welding and related activities associated with the fabrication of the San Francisco Oakland Bay Self Anchored Suspension Bridge at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

OBG Trial Assembly Yard

Segment 12BE/12CE

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a UT repair on a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated OBE12C-001, Bottom Plate transverse splice. The welder is identified as #040320 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-345-SMAW-4G (4F)-FCM-repair-1 for WR20190.

Segment 12CW

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of Complete Joint Penetration (CJP) weld joint. The Weld joint is designated SEG3006A-011, Bottom Plate to Side Plate hold back weld. The welder is identified as #057333 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of Complete Joint Penetration (CJP) weld joint. The Weld joint is designated SEG3006A-012, Bottom Plate to Side Plate hold back weld. The welder is identified as #040656 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

For the above mentioned welding activities ZPMC Quality Control (QC) Inspector is identified as Wang Li Yang and Zhou Peng. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Trial assembly

Due to limited staffing of ZPMC personnel and inclement Weather, work was limited in the OBG Trial Assembly

CB18 and CB19

QA Inspector randomly walked at the above mentioned locations throughout the shift duration. It was observed that no fabrication was performed during this shift.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372 , who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
----------------------	---------------	-----------------------------

Reviewed By:	Dsouza,Christopher	QA Reviewer
---------------------	--------------------	-------------