

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021572**Date Inspected:** 16-Nov-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Xu Le Feng /Qiu Wen**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Bike Path**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Scott Leavitt, was present during the times noted above for observations relative to the work being performed.

Bay 10 – Tower Shop

In Process Inspection FCAW

This QA Inspector observed the following work in progress: FCAW welding of weld joint 123 located on BK004A8-027. Welder is identified as 036364. ZPMC Quality Control (QC) is identified as Qui Wen. The welding variables recorded by QC appeared to comply with the Applicable WPS.

This QA Inspector observed the following work in progress: FCAW welding of weld joint 022 located on BK004A4-030. Welder is identified as 040302. ZPMC Quality Control (QC) is identified as Qui Wen. The welding variables recorded by QC appeared to comply with the Applicable WPS.

This QA Inspector observed the following work in progress: FCAW welding of weld joint 035 located on BK004A4-030. Welder is identified as 052075. ZPMC Quality Control (QC) is identified as Qui Wen. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Bay 11 – Tower Shop

In Process Inspection FCAW

---

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

---

This QA Inspector observed the following work in progress: FCAW welding of weld joint 002 located on BK004A3-019. Welder is identified as 040723. ZPMC Quality Control (QC) is identified as Xu Le Feng. The welding variables recorded by QC appeared to comply with the Applicable WPS.

This QA Inspector observed the following work in progress: FCAW welding of weld joint 073 located on BK004A6-019. Welder is identified as 205646. ZPMC Quality Control (QC) is identified as Xu Le Feng. The welding variables recorded by QC appeared to comply with the Applicable WPS.

### Visual Inspection

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 07370.

This QA inspector performed VT of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel.

The members are identified as:

BK004A3-023-025, 026

BK004A7-023-001, 002, 007, 008, 217, 228, 229, 230, 061, 062, 067, 068

BK004A3-023-051, 052

BK004A7-023-013, 014, 019, 020, 140, 141, 142, 143, 073, 079, 080

BK004A4-023-014

BK004A7-023-025, 026, 158, 159, 085, 086

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 07378.

This QA inspector performed VT of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel.

The members are identified as:

BK004A5-025-004

BK004A3-025-005

BK004A2-025-001, 003, 004, 005, 006

BK004A3-025-019, 020, 043, 044, 021, 022, 045, 046

BK004A4-025-006, 007, 032, 033, 058, 059, 004, 005, 030, 031, 050, 051

BK004A6-025-072, 073

BK004A5-025-112, 115, 118, 121, 014, 015, 034, 035, 054, 055, 074, 075, 110, 111, 113, 114, 116, 117, 119, 120

### Magnetic Particle Inspection (MT)

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 07370.

This QA inspector performed MT of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date.

The members are identified as:

BK004A3-023-025, 026

BK004A7-023-001, 002, 007, 008, 217, 228, 229, 230, 061, 062, 067, 068

BK004A3-023-051, 052

---

---

# WELDING INSPECTION REPORT

( Continued Page 3 of 3 )

---

---

BK004A7-023-013, 014, 019, 020, 140, 141, 142, 143, 073, 079, 080

BK004A4-023-014

BK004A7-023-025, 026, 158, 159, 085, 086

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 07378.

This QA inspector performed MT of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date.

The members are identified as:

BK004A5-025-004

BK004A3-025-005

BK004A2-025-001, 003, 004, 005, 006

BK004A3-025-019, 020, 043, 044, 021, 022, 045, 046

BK004A4-025-006, 007, 032, 033, 058, 059, 004, 005, 030, 031, 050, 051

BK004A6-025-072, 073

BK004A5-025-112, 115, 118, 121, 014, 015, 034, 035, 054, 055, 074, 075, 110, 111, 113, 114, 116, 117, 119, 120

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



## Summary of Conversations:

No relevant conversations.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang at 15000422372, who represents the Office of Structural Materials for your project.

---

**Inspected By:** Leavitt, Scott

Quality Assurance Inspector

**Reviewed By:** Clifford, William

QA Reviewer

---