

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024982**Date Inspected:** 07-May-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Xu Le Feng**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

BAY#10

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint #002 located on Bike path BK010A2-001. Welder is identified as 052930. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS-B-P-2112.

Weld joint #241 located on Bike path BK010A3-001. Welder is identified as 040302. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS-B-P-2112.

Weld joint #021 located on Bike path BK010A2-001. Welder is identified as 052930. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS-B-P-2112.

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

---

Weld joint #248 located on Bike path BK010A3-001. Welder is identified as 040302. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS-B-P-2112.

BAY#11

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint #43 located on Tower head component BK011A1-001. Welder is identified as 041271. ZPMC Quality Control (QC) Inspector is identified as Yu Dong Ping. The welding variables recorded by QC appeared to comply with the WPS-B-P-2212-Tc-U4c.

Weld joint #43 located on Tower head component BK011A1-001. Welder is identified as 044551. ZPMC Quality Control (QC) Inspector is identified as Yu Dong Ping. The welding variables recorded by QC appeared to comply with the WPS-B-P-2212-Tc-U4c.

Flux Cored Arc Welding (FCAW):

Weld joint #044 located on Bike path BK012A1-001. Welder is identified as 044541. ZPMC Quality Control (QC) Inspector is identified as Wang Chuang Xin. The welding variables recorded by QC appeared to comply with the WPS-B-P-2211-B-U2b.

Weld joint #043 located on Bike path BK012A1-001. Welder is identified as 041271. ZPMC Quality Control (QC) Inspector is identified as Wang Chuang Xin. The welding variables recorded by QC appeared to comply with the WPS-B-P-2212-Tc-U4c.

Weld joint #044 located on Bike path BK012A1-001. Welder is identified as 046704. ZPMC Quality Control (QC) Inspector is identified as Wang Chuang Xin. The welding variables recorded by QC appeared to comply with the WPS-B-P-2211-B-U2b.

Weld joint #043 located on Bike path BK012A1-001. Welder is identified as 041713. ZPMC Quality Control (QC) Inspector is identified as Wang Chuang Xin. The welding variables recorded by QC appeared to comply with the WPS-B-P-2212-Tc-U4c.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

**Summary of Conversations:**

No Relevant Conversations.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Thomas Ho - 15002048250, who represents the Office of Structural Materials for your project.

---

---

# WELDING INSPECTION REPORT

*( Continued Page 3 of 3 )*

---

---

---

<b>Inspected By:</b>	Kumar,Sandeep	Quality Assurance Inspector
----------------------	---------------	-----------------------------

---

<b>Reviewed By:</b>	Clifford,William	QA Reviewer
---------------------	------------------	-------------

---