

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-025552**Date Inspected:** 30-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	OBG	

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Vikram Singh was present during the times noted above for observations relative to the work being performed at ZPMC.

BLAST INSPECTION

Blast Shop-1


OBG Lift 14E

This Quality Assurance (QA) Inspector performed Post blast visual inspection (VT) of external surfaces of edge plate, anchor plates, bottom plates under CB and floor beams (FL3) in between PP126 to PP127 of the OBG 14E {CB Side}, Areas marked up for weld repair were recorded on a weld map for future repair. Areas requiring additional grinding were marked by QA and repaired by ZPMC personnel. For further information, please see the attached pictures below:

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey-15000026784, who represents the Office of Structural Materials for your project.

Inspected By:	Singh, Vikram	Quality Assurance Inspector
Reviewed By:	Riley, Ken	QA Reviewer
