

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Casey, William**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-026509**Date Inspected:** 11-Oct-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Job Site**CWI Name:** N / A**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** S.A.S. components**Summary of Items Observed:**

The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI reviewed contract documents at pier 7. The QAI used approved weekly welding report submittals and cross referenced the welding and inspection status as reported with QA records to identify the overall weld status. The QAI continued reviewing welding report package 83 for conformance with the contractor requirements. This work was in progress at the end of the shift.

The QAI was requested to sample fastener components that have been delivered to the Pier 7 job site. The QAI met with Caltrans Transportation Engineer Bob Brignano and was provided access to the fastener components. The QAI was also provided with copies of the pertinent manufacturing certification documents. The QAI pulled random samples to satisfy the contract requirements for verification. The QAI assigned lot numbers B212-035-11 and B212-036-11 and generated TL-102 forms with the pertinent information. The QAI was informed that some of the fastener components are intended to be used temporarily but will be tested in case the contractor will install them permanently. The QAI delivered to the samples to Translab and retrieved the A490 Geomet fasteners that were not visually acceptable. The QAI was informed by Mr. Brignano that the contractor may request to utilize the fasteners at a later time.

Summary of Conversations:

The QAI relayed the status of the report reviews and A490 sample status to the QAI Lead Bill Levell. Except as described above, there were no other notable conversations.

WELDING INSPECTION REPORT

(*Continued Page 2 of 2*)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy (510) 385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Croff,Scott	Quality Assurance Inspector
----------------------	-------------	-----------------------------

Reviewed By:	Levell,Bill	QA Reviewer
---------------------	-------------	-------------