

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Casey, William**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-028618**Date Inspected:** 16-Oct-2012**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1730**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** jobsite**CWI Name:****CWI Present:**

Yes No

**Inspected CWI report:** Yes No N/A**Rod Oven in Use:**

Yes No N/A

**Electrode to specification:** Yes No N/A**Weld Procedures Followed:**

Yes No N/A

**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:**

Yes No N/A

**Approved Drawings:** Yes No N/A**Approved WPS:**

Yes No N/A

**Delayed / Cancelled:**

Yes No N/A

**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Quality Assurance Inspector (QAI) Matthew Daggett was at the American Bridge/Fluor (ABF) job site at the San Francisco/Oakland Bay Bridge in California between the times noted above in order to perform clerical support tasks in the office, and to monitor Quality Control functions and the in process work being performed by ABF personnel:

This QAI spent the majority of the day creating a spread sheet to track RWR's. The spread sheet will be used not only for tracking purposes but as a guide for the inspection team to more readily access the RWR's for inspection purposes. This QAI has almost completed the spreadsheet for all RWR's written in the month of October 2012.

The QAI also updated the spreadsheet tracking the status of Non-Destructive Testing (NDT) on the project, and filed a hard copy of the NDT reports in the proper binder.

Scott Croft provided further training by explaining the CALTRANS material release process to this QAI. The Contractor at varying intervals has cut/fabricated materials that need inspected at their Warehouse here at the pier 7 complex.

**Summary of Conversations:**

See body of report.

**Comments**

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Gary Thomas 916-764-6027, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Daggett, Matt	Quality Assurance Inspector
<b>Reviewed By:</b>	Reyes, Danny	QA Reviewer

---